



M.: 9873840014

SAHIL AC REPAIR AND SERVICE

All Type of Air Condition, Refrigeration and Microwave
Geyser and Water Heater, Repair Service, Installation
Ground Floor, G-180/1, Gali No. 8, Mohan Baba Nagar, Tajpur Extn.,
Badarpur, New Delhi - 110044 E-mail : contact@sahilaccare.in

Rate Card

Electrical Parts

Non-Inverter PCB repaired	Rs 1299
Inverter PCB repaired	Rs 3599
Replace LVT	Rs 700 Rs 299 (Labour)
Capacitor 2-5 mfd	Rs 250 Rs 299 (Labour)
Capacitor 10-25 mfd	Rs 400 Rs 299 (Labour)
Capacitor 35-50 mfd	Rs 400 Rs 299 (Labour)
Capacitor 50-60 mfd	Rs 400 Rs 299 (Labour)
Replace sensor	Rs 350 Rs 299 (Labour)
Contactoer replaced	Rs 500 Rs 299 (Labour)
Contactoer Daikin/ O-General	Rs 1500 Rs 299 (Labour)
Convert PCB with remote	Rs 1500



Fan Motors

Description	Service Charge
Fan motor - Split AC	Rs 1599 Rs 299 (Labour)
Blower motor - Split AC	Rs 2150 Rs 299 (Labour)
Blower replaced	Rs 999 Rs 299 (Labour)
Replace Flap/Swing Motor	Rs 400 Rs 299 (Labour)
Motor Bearing Change	Rs 1000
Fan motor - Window AC	Rs 2500 Rs 299 (Labour)
Noise issue repair	□ 0 Rs 299 (Labour)



Service & installation

Description	Service Charge
Install	Rs 1499
Uninstall	Rs 549
Window Ac insrall	Rs 599
Window Uninstall	Rs 399
1 meter copper pipe set (with insulation, wire)	Rs 850
Split AC Wall stand	Rs 550
Outdoor unit reinstalled	Rs 799
Indoor unit reinstalled	Rs 699
Drain pipe (1m)	Rs 100
Fastner complete set	Rs 150
Floor stand	Rs 550
Universal back plate	Rs 300
Power Jet AC Service (Window)	Rs 449
Power Jet AC Service (Split)	Rs 499
Service lite	Rs 400
Anti-rust deep clean AC service	Rs 499
Foam & Power Jet AC Service (Split)	Rs 599
Foam & Power Jet AC Service (Window)	Rs 499



Minor Repairs

Description	Service Charge
Water Leakage Repaired- Split AC	Rs 0 Rs 499 (Labour)
Adjust Grill Locks	Rs 0 Rs 299 (Labour)
Adjust pipe and tight compressor screw	Rs 0 Rs 299 (Labour)
Connector wires replaced (1m)	Rs 100 Rs 299 (Labour)
Tighten/ Replace Thimble	Rs 50 Rs 299 (Labour)
External Dust/stick removal	Rs 0 Rs 299 (Labour)
Insulation refix	Rs 0 Rs 299 (Labour)
Drain pipe adjust	Rs 0 Rs 299 (Labour)
Noise adjustment in motor	Rs 0 Rs 299 (Labour)
Noise adjustment in blower	Rs 0 Rs 299 (Labour)
Noise adjustment in cabinet	Rs 0 Rs 299 (Labour)
Noise adjustment in swing flap	Rs 0 Rs 299 (Labour)
Water Leakage Repaired- Window AC	Rs 0 Rs 299 (Labour)

Others Parts

Description	Service Charge
	Rs 500
Water tray	Rs 299 (Labour)
Stabilizer repair	Rs 1200
Drain pipe adjust	Rs 100
Sleeves (per piece)	Rs 50
Insulation refix	Rs 100
	Rs 0
Noise issue repair	Rs 299 (Labour)
	Rs 0
Stabilizer connection	Rs 299 (Labour)
	Rs 700
AC fan blade	Rs 299 (Labour)
	Rs 1500
Grill Cover	Rs 299 (Labour)
	Rs 400
Swing blade replaced	Rs 299 (Labour)
Universal remote	Rs 700
Compressor grommets set	Rs 299
Rubber washer (1 pc)	Rs 50



Gas Charging

Description	Service Charge
Gas Charging	Rs 2299
Replacement Compressor (1 Ton)	Rs 4000
Replacement Compressor (1.5 Ton)	Rs 4500
Replacement Compressor (2 Ton)	Rs 5000
Flair nut replaced	Rs 150
Cooling Coil / Condenser Coil repair	Rs 0 Rs 500 (Labour)
Copper Coil Condensor 1 ton Split	RS 3500
Copper Coil Condensor 1.5 ton Split	Rs 4000
Copper Coil Condensor 2 ton Split	Rs 4500
Service valve replaced (1 Pc)	Rs 400
Copper Cooling Coil (Split AC)	Rs 6000
Capillary and filter replaced	Rs 350
Compressor 0.8-1 ton	Rs 6500
Compressor 1.5 ton	Rs 7500
Compressor 2 ton	Rs 9200
Expansion valve replaced	Rs 1200
Dead nut (1 pc)	Rs 50
U Band replaced (1 pc)	Rs 50
Pin Valve for window AC	Rs 50
Copper Cooling Coil/Condensor Coil (Window AC)	Rs 4500

